


AIR SAW

EXPLODED VIEW

SP-7600



PARTS LIST

Index No.	Parts No.	Description	Qty. Per tool
2	7600-02	Blade Guide	1
3	7600-03	Saw Blade	1
4	7600-04	Blade Chuck	1
6	7600-06	Set Screw	2
7	7600-07	Hex. Bolt	8
8	7600-08	Spring Washer	8
9	7600-09	Guide	1
10	7600-10	Piston Housing	1
11	7600-11	Housing Cover	1
12	7600-12	Front Cushion Spring	1
13	7600-13	Set Screw	4
18	7600-18	Rear Cushion Spring	1
19	7600-19	Gasket	1
20	7600-20	Valve Block	1
21	7600-21	Valve Spring	1
22	7600-22	Valve Ball	1
23	7600-23	O-Ring	1
24	7600-24	O-Ring	1
25	7600-25	Valve Bush	1
26	7600-26	Throttle Pin	1
27	7600-27	Safety Lever	1
28	7600-28	Roll Pin	1
29	7600-29	Adaptor	1
30	7600-30	Hex. Key Wrench	1

Index No.	Parts No.	Description	Qty. Per tool
31	7600-31	O-Ring	1
32	7600-32	Piston Assembly	1